DAILY WORK ORDER	
Work Site Bossert Manufacturing	Work Period 5/31/87
	OSC Joseph Rotola
Work Planned/Authorized	Work Accomplished From
1 ) Callact mannlan form flamm	Previous Work Order
1.) Collect samples from floors walls, soils & machines 2.) Pump aqueous material from sumps into 50K pool	Yes No Continues  1.) ( ) ( ) (x)  2.) ( ) ( ) (x)  3.) ( ) ( ) (x)  4.) ( ) ( ) (x)  5.) ( ) ( ) (x)
3.) Site preparation by clearing & stockpiling	3.) () () (X) 4.) () () (v)
floor debris	5.) () () (x)
4.) Install electrical ap-	6.) () (x)
purtenances for the provision	
of interior lighting 5.) Continue to remove & stock-	COMMENTS: Procure one liner for
pile sump debris	50K pool
6.) Design and construct sump covers	<b>5</b>
to meet OSHA requirements	
Equipment Planned/Authorized	Equipment Used From Previous Day
580D Backhoe  Decon Trailer (1) 12K pools  Command Post; Mini-Trackhoe  (1) Car; Pneumatic Forklift  (2) Pick-up Trucks (2) Pobents	All Authorized
(2) Pick-up Trucks (2) Bobcats (1) Break Trailer; 3CY Dumpster (1) 6.5KW Generator (3) Hilti guns (1) 5.0KW Generator (2) Vans	COMMENTS: N/A
<ul> <li>(1) Double Diaphram Pump</li> <li>(2) 3/4" Electrical Pumps</li> <li>(12) Air cylinders; (1) Hydraulic ha</li> <li>(1) Aerial Lift; (2) 2" Submersible</li> <li>(1) 50K pool (3) Propane tanks</li> </ul>	ammer
(1) Electrician (1) (1) Laborer (1)	Response Manager Foreman (Level 2) Field Clerk
·	) Clean-up Technician (Level 2) ) Clean-up Technician (Level 1)
Contractor Signature	CSC Signature
Date 5/31/87	Dat 5/81/87
and and the the the time of the time time the time time time time time time time tim	10 per 195 min and gen fire in a 100 min and and and and and and an analysis and an analysis and an an and an and an